
Product Name: SD9364-EHL
Release Version: 0114a
Date: 2019/05/14
Product Type ☒ Camera ☐ NVR ☐ Software

New Feature:

N/A

Changed Feature:

N/A

Bugs Fixed:

- Fixed Chrome web UI no audio with issue on Windows 10.
- Fixed cannot focus on near object issue.
- Fixed privacy mask may mask wrong place issue when the tilt angle is large.
- Fixed an issue in which focus window works on wrong area instead of custom define area.

Release Version:0113a

Date:2019/04/15

New Feature:

N/A

Changed Feature:

- Upgrade ONVIF version to 18.06
- Upgrade Web API to 0311c.
- Change the default access name for HTTP/RTSP stream format.
- Upgrade Genetec package to 1.0a.a0.3.2.

Bugs Fixed:

- Fixed an issue in which video setting page cannot be displayed after upgrade to 0109a.
- Fixed CVE-2019-10256, an authentication bypass vulnerability.
- Fixed camera IP change to 127.0.0.1 issue after reboot when Stratocast is enabled.

Release Version:0109a

Date:2018/12/06

New Feature:

N/A

Changed Feature:

- Upgraded Web API to 0311b.
- Upgraded smart SD card version to 1.0.1.4.
- Remove "Customsafe100" from Configuration > Network > DDNS > Provider list.

- Change from pop-up window to notification when uploading configuration file.
- Disable CSRF mechanism after reset to factory mode and will be enable after setting password in factory mode.

Bugs Fixed:

- Fixed CVE-2018-18244, persistent XSS via HTTP Referer header.
- Fixed CVE-2018-18005, DOM-Based XSS vulnerability in camera event_script.js
- Fixed CVE-2018-18004, a notification will show on camera home page when hidden service has been enabled.
- Fixed an issue in which firmware upgrading gets stuck if turn on Trend Micro.
- Fixed Trend Micro display incorrect status in package management page.
- Fixed Trend Micro IoT Security incorrect status in Trend Micro setting page.
- Fixed Trend Micro current version become invisible after upgrade signature issue.
- Fixed failed to upload VADP package issue.