Release Note

Product Name	<IP61x4-VVTK>
Release Version	<0102f>
Date	<2006/06/28>

New Features:	
01.	N/A
Changed Features:	
01.	N/A
Bug fixed:	
01.	Bug fixed for the re-register of safe100 after 10 minutes
02.	Change the time out to 60 seconds for safe100 register to avoid the failure of register.
03.	Add the retry times for DHCP to solve the problem of getting IP in wireless mode