Release Note

Product Name: <MA9321-EHTV >
Release Version: <0114f>
Date: <2021/7/6>
Product Type ☒ Camera ☐ NVR ☐Software

New Feature:

- N/A.

Changed Feature:

- N/A.

Bugs Fixed:

- Fixed the camera out of focus in some circumstances.
- Fixed the camera defocus after the camera reboot.

Release Version: <0122a_Beta2>
Date: 2020/5/4
New Feature:

- N/A.

Changed Feature:

- Remove the customized script function on the event settings page.

Bugs Fixed:

- Fixed CVE-2020-11949, Allow an authenticated user to obtain arbitrary files from a camera's local filesystem via testserver.cgi.
- Fixed CVE-2020-11950, Allow an authenticated user to upload and execute a script (with resultant execution of OS commands) via eventscript.cgi.

Known Issue:

- If the snapshot and log file is sent when the event trigger type is set to smart SD, users will not able to search them in Content management page.
- In digest mode, users will need to login more than one time and may need to re-login when switching page.
- If sending a file to the NAS event action, the NAS will not receive the file and the mounting status might become Error.
- If you launch multi-tab to view camera streaming, it will display streaming on first tab and the rest will show black image.

- It will display black image once change the camera URL from http to https.
- If you enable/disable the flip/mirror/rotation, it will not reset the focus window.
- If upgrades the firmware from 0114c to 0122a_Beta2, the zoom bar of channel 1 will go to the left side.

Release Version: <0122a_Beta1>
Date: 2019/12/27
New Feature:
- Add license expiration notice in Trend Micro event.
- Add function of “Stop License with stop service code” in Trend Micro event.

Changed Feature:
- Upgrade VADP version to 1.4.2.2.
- Upgrade Trend Micro package version to v1.2d.a1.5.2.
- Upgrade Stratocast package to v1.1a.a1.4.2.
- Upgrade embedded Genetec version to 2.0.4.1.
- Not support play streaming via QuickTime.
- Fixed CVE-2019-19936, remove and not support eventtask.cgi

Bugs Fixed:
- Enhanced error handling for input /cgi-bin/viewer/video.jpg with illegal parameters.
- Enhanced error handling for /cgi-bin/admin/setparam.cgi?network_http_port.
- Enhanced SD card status display mechanism.
- Fixed zoom/focus bar incorrect issue.
- Fixed seamless recording not resuming the recording correctly issue.
- Fixed timeshift function not work issue.
- Fixed service name will return to default after upgrading firmware.
- Fixed upgrade firmware failed in specific circumstance.
- Fixed cannot display webpage issue when connect to camera by using not default https port.
- Fixed could not connect to camera via public IP once enable PPPoE.
- Fixed Stratocast reconnection mechanism to wait 30 second re-attempt cooldown period to avoid Stratocast server put camera connection into black list.
- Fixed zoom/focus position is not correct issue after upgrade firmware from 0113b to 0120b_SA2019002.
- Fixed zoom/focu position will go the left side after restore expect Focus position.

Known Issue:

- If the snapshot and log file is sent when the event trigger type is set to smart SD, users will not able to search them in Content management page.
- In digest mode, users will need to login more than one time and may need to re-login when switching page.
- If sending a file to the NAS event action, the NAS will not receive the file and the mounting status might become Error.
- If you launch multi-tab to view camera streaming, it will display streaming on first tab and the rest will show black image.
- It will display black image once change the camera URL from http to https.

Release Version: <0120b_SA2019002>
Date: <2019/08/23>
New Feature:
- Support Bonjour.
- Support Trend Micro event.

Changed Feature:
- Upgrade VADP version to 1.4.1.0.
- Embedded Genetec protocol.
- Removed Genetec package.
- Removed DDNS forget key button.

Bugs Fixed:
- Fixed CVE-2019-14457, Stack-based buffer overflow via a crafted HTTP header.
- Fixed CVE-2019-14458, Allow a denial of service via a crafted HTTP header.
- Fixed CVE-2019-14477 SACK Panic (Linux >= 2.6.29).
- Fixed CVE-2019-11478 SACK Slowness (Linux < 4.15) or Excess Resource Usage (all Linux versions).
- Fixed CVE-2019-11479 Excess Resource Consumption Due to Low MSS Values (all Linux versions).

Known Issue:
- If the snapshot and log file is sent when the event trigger type is set to smart SD, users will not able to search them in Content management page.

Release Version: <0114c>
Date: <2019/06/27>

New Feature:

- N/A

Changed Feature:

- N/A

Bugs Fixed:

- Fixed camera will auto focus many times once restore camera to factory default.
- Fixed the “Disconnect” button of Connection management cannot be used.
- Fixed an issue of Channel 2, 3, 4 cannot control IR by turn on built-in IR illuminator and Anti-overexposure in night mode.

Release Version: <0113a>
Date: <2019/04/17>
New Feature:

- N/A

Changed Feature:

- N/A

Bugs Fixed:

- Fixed CVE-2019-10256, an authentication bypass vulnerability.

Release Version: <0100l>
Date: <2019/02/25>
New Feature:

- First release.

Changed Feature:

- N/A

Bugs Fixed:

- N/A