

---

Product Name: <IP9181-H>  
Release Version: <0113b>  
Date: <2019/05/22>  
Product Type ☒ Camera ☐ NVR ☐ Software

---

## **New Feature:**

N/A

## **Changed Feature:**

- Upgrade ONVIF version to 18.06
- Upgrade Web API to 0311c.
- Upgrade Genetec package to 1.a0.3.2.
- Change the default access name for HTTP/RTSP stream format.

## **Bugs Fixed:**

- Fixed CVE-2019-10256, an authentication bypass vulnerability.
- Fixed Genetec package crash issue when smart motion is enabled.

## **Release Version: 0109a**

**Date: 2018/12/11**

## **New Feature:**

N/A

## **Changed Feature:**

- Upgraded Web API to 0311b.
- Upgraded smart SD card version to 1.0.1.4.
- Remove "Customsafe100" from Configuration > Network > DDNS > Provider list.
- Change from pop-up window to notification when uploading configuration file.
- Disable CSRF mechanism after reset to factory mode and will be enable after setting password in factory mode.

## **Bugs Fixed:**

- Fixed CVE-2018-18244, persistent XSS via HTTP Referer header.
- Fixed CVE-2018-18005, DOM-Based XSS vulnerability in camera event\_script.js
- Fixed CVE-2018-18004, a notification will show on camera home page when hidden service has been enabled.
- Fixed Trend Micro package cannot be enable issue.
- Fixed an issue in which firmware upgrading gets stuck if turn on Trend Micro.
- Fixed Trend Micro display incorrect status in package management page.
- Fixed Trend Micro IoT Security incorrect status in Trend Micro setting page.
- Fixed Trend Micro current version become invisible after upgrade signature issue.
- Fixed an issue in which smart FPS works incorrectly when WDR Pro is enable.
- Fixed failed to upload VADP package issue.